

SAPC-10716
Copy 2 of 5

13 November 1956

MEMORANDUM FOR: Contracting Officer

25X1A

SUBJECT : Comments on IN-08307 from [REDACTED] to [REDACTED] 25X1A

1. The first sentence of Paragraph 2 is without foundation. 25X1A
[REDACTED] although instructed to monitor System Three work as a fifth priority function (System Four, System One, System Four read-out and System One read-out problems are of higher priority), has not contacted the Ramo-Wooldridge people on System Three, has not seen any of the hardware nor test results and has not been consulted by R-W personnel on any phase of the System Three receiver.

2. By phone on 5 November, Burt stated that seven System Three's, in addition to the two delivered, would be ready within a week. They are ready excepting for an insulation breakdown problem. Burt stated that he would supply replacement boards to Detachment B for the two they have and expedite any other maintenance parts requested by the Detachment.

3. Paragraph 7 - Special Equipment. The noisy effect mentioned has been found to exist in part at least, within the battery-powered transistorized preamplifier obtained by [REDACTED] from Commo. 25X1A

4. The antenna tuning range problem was the result of insufficient test facility at R-W and has been resolved.

[REDACTED] 25X1A

ESO/JFS:jdd (13 Nov 56)

Distribution:

Copies 1 and 2 - [REDACTED]
3 and 4 - ESO
5 - Project Chron

25X1A

DOCUMENT NO. _____
NO CHANGE IN CLASS. ☒
☐ DECLASSIFIED
CLASS. CHANGED TO: TS S C 2012
NEXT REVIEW DATE: _____
AUTH: RH JS-2
DATE: 15/1/82 REVIEWER: 064540